PV1
Display Tare Weight

description	MULTI-APPLICATION WEIGHT-TARE DISPLAY INDICATED FOR WEIGHING OPERATIONS WITH HIGH RELIABILITY, PRECISION AND SIMPLICITY.
highlights	ANALOG | BACKLIT LCD DISPLAY | STAINLESS BOX | EC APPROVAL
functions	Basic functions: zero, tare, accumulations● Advanced functions: filters, zero search, high resolution, PC connection, external printer or weight repeater, animal weighing, piece counter ● Applications: weighing platform, analogue weighbridge, bar weigher, weighbridge silos, weighbridge;
specifications	- Power supply: 7.5 V DC (External power supply); - Approvals: EN 45501:2015; OIML R 76-1 (2006); - Load cells: analog; - Communications: 1x RS232 (PC / Repeater / Printer); - Construction: Stainless steel; - Dimensions: 258x258x40 mm; - Display: backlit LCD; digits 6x28 mm; - Mounting: wall / table; - Weight: 1.8 kg; - Protection: IP55; - Keys: on/off, zero/tare, function, count, right, up; - Operating temperature: -10 °C / +40 °C;

models	Reference	Drums	Printer
	PV1	No	No
	PV1/bat	Yea	No
	PV1/i/bat	Yea	Yea